


Sand Blasting Chart




Completely covered in mill scale



Mill scale has started to flake, light rusting occurs



Mill scale has flaked off complete rusting has taken place



Pitting and complete rusting has occurred



	Brush-Off SSPC-SP7	Commerical SSPC-SP6	Near-White Metal SSPC-SP10	White Metal SSPC-SP5
